

HASTELLOY[®] N alloy

Average Fatigue Data

Rotating

Form	Condition	Test Temperature	Stress for Failure in 10 ⁶ Cycles:
Sheet	Heat-treated at 2150°F (1177°C), RAC	1100 °F	47,500 psi
		1300 °F	38,000 psi
		1500 °F	23,000 psi